

# VC-TR41 Firmware Release Note

| Release Date | Version | Description   | Note                                |
|--------------|---------|---|-------------------------------------|
| 2026/6/2     | VUF119  | <p><b>New Features</b></p> <ol style="list-style-type: none"> <li>Added UAC output toggle switch.</li> <li>Added support for configuring polygon-shaped blocked area.</li> <li>Added Smart AF feature.</li> <li>Added PTZ-only function for preset recall.</li> <li>Added Adaptive LED mode to replace the previous LED modes.</li> </ol> <p><b>Improvements</b></p> <ol style="list-style-type: none"> <li>Accelerated tracking speed for a single person when in Auto Framing mode and Partition Framing mode.</li> <li>Added Framing Size and Head Position adjustment options to Auto Framing mode and Partition Framing mode.</li> </ol> <p><b>Bug Fixes</b></p> <ol style="list-style-type: none"> <li>Fixed an issue causing intermittent screen color abnormalities.</li> </ol> |                                     |
| 2026/2/26    | VUF116  | <p><b>Improvement</b></p> <ol style="list-style-type: none"> <li>Improved the startup behavior to optimize motor operation performance</li> </ol>   |                                     |
| 2026/1/12    | VUF114  | <p><b>Bug fix</b></p> <ol style="list-style-type: none"> <li>Fixed the issue where the Static IP could not be stored properly after rebooting.</li> </ol>   |                                     |
| 2025/12/08   | VUF113  | <p><b>Bug fix</b></p> <ol style="list-style-type: none"> <li>Optimized memory access to reduce unnecessary write operations</li> </ol>  |                                     |
| 2025/10/03   | VUF110  | <p><b>Improvement</b></p> <ol style="list-style-type: none"> <li>Improved the tracking performance.</li> <li>Zoom certification has been acquired.</li> </ol> <p><b>Bug fix</b></p> <ol style="list-style-type: none"> <li>Fixed the bug where the camera sometimes freezes after plugging in the power.</li> </ol>   | <a href="#">Certified for Zoom.</a> |
| 2025/8/29    | VUF107  | <p><b>Bug fix</b></p> <ol style="list-style-type: none"> <li>Adjusted the tilt control value to ensure smoother PTZ movement.</li> </ol>  |                                     |
| 2025/06/26   | VUF105  | First Version   |                                     |

