LC200 Firmware Release Note

| Release Date | Version | Description | Note |
|--------------|-----------|---|------|
| 2025/8/15 | V4.8.0.70 | New Feature | |
| | | 1. Added API commands for Kaltura appToken authentication. | |
| | | Bug fix | |
| | | 1. Fixed a bug where the PGM audio output had no sound. | |
| | | 2. Fixed LC200 connection issue with CaptureVision Mini Controller. | |
| | | 3. Fixed Backup Settings not applying to account with Director permission. | |
| 2025/2/11 | v4.8.0.69 | New Feature | |
| | | 1. Added a new authentication method for Kaltura backup. | |
| | | 2. Added a connection test button in the backup section on webpage. | |
| | | Improvement | |
| | | 1. NAS no longer need to be remounted after restarting the LC200. | |
| | | 2. Logs can now retain data for a longer period. | |
| | | Bug fixe | |
| | | 1. Fixed an issue where .ics files could not be imported into the LC200. | |
| 2024/04/19 | v4.8.0.66 | New Feature | |
| | | 1. Added a Partner ID column in Backup Settings for Kaltura Server backup. | |
| | | 2. When choosing Panopto in Backup setting, you can upload the files to the designated ID | |
| | | folder. | |
| | | 3. Added a USB drive backup function in Backup Settings. | |
| | | 4. Individual MP4 files can now be uploaded instead of entire folder when using FTP or NAS. | |
| | | 5. Added a Customized Mode, so you can choose which video sources to record. | |
| | | 6. Added additional time options for synchronization intervals. | |
| | | Bug Fixed | |
| | | 1. Fixed a bug where the record file might get stuck in processing. | |
| | | 2. Fixed the bug where tag information would be deleted after recording a recurring event. | |

| Release Date | Version | Description | Note |
|--------------|-----------|--|------|
| 2023/08/07 | V4.8.0.63 | Improvement | |
| | | Support RTMP streaming on Microsoft Teams live events. | |
| | | 2. Fixed that Standby or Wake up function is not working. | |
| | | 3. Add retry method to improve recording fail to upload on Panopto. | |
| 2023/05/31 | V4.8.0.59 | Improvement | |
| | | 1. Fixed the Audio display wrong after unmute. | |
| | | 2. Fixed the HDMI source randomly drop issue. | |
| | | 3. Fixed Macro fail issue when uses Director account. | |
| | | 4. Improved safety and security on Webpage interface. | |
| 2023/02/03 | V4.8.0.57 | Improvement | |
| | | 1. RS485 Connection bug fixed. | |
| 2022/11/15 | V4.8.0.51 | Improvement | |
| | | 1. The issue of Failure upload 2GB file while using NAS SMB 2.0. | |
| 2022/10/20 | v4.8.0.50 | New Features | |
| | | 1. Added function that names the record file and the re-upload file. | |
| | | 2. Added the PGM screen on Webpage. | |
| | | 3. Added more tracking cameras module. (VC-TA50, VC-TR40) | |
| | | 4. Added schedule record / webcasting functions that integrated with Kaltura | |
| | | Improvement | |
| | | 1. Bug fixed OBS rtsp stream shut down issue. | |
| | | Bug fixed that Overlay can't be changed. | |
| 2022/05/10 | v4.8.0.42 | Improvement | |
| | | 1. Corrected the words of "Intermission" on the GUI page. | |
| | | 2. Fixed the recording file issue. | |
| | | 3. Added crash protection mechanism. | |
| | | 4. Removed Telnet connection for security purpose. | |
| 2022/01/11 | v4.8.0.41 | New Features | |

| Release Date | Version | Description | Note |
|--------------|-----------|--|------|
| | | 1. Added Record pause / bookmark function. | |
| | | | |
| | | Improvement | |
| | | 1. Improved screenshot quality. | |
| 2021/11/22 | v4.8.0.35 | New Features | |
| | | 1. Added the function that allow users to upload their own Intermission screen. | |
| | | 2. Added Front panel lock function. | |
| | | 3. Added Marco function, the users can set different settings for the IP cameras of channe1~4, | |
| | | and also add tracking related settings. | |
| | | 4. Added the option to set SMB version on NAS settings page. | |
| | | | |
| | | Improvement | |
| | | 1. Fixed issue: stuck on the booting page when power on. | |
| 2021/09/17 | v4.8.0.30 | New Features | |
| | | 1. Added Multi-Stream to Panopto. | |
| | | 2. Added Record Settings to make the size of the video file smaller. | |
| 2021/06/22 | v4.8.0.22 | New Features | |
| | | 1. Support Http API to control LC200 with Lumens Deployment Tools. | |
| | | 2. Support VC-TR1 tracking on/off function. | |
| | | 3. Added Intermission function. | |
| | | | |
| | | Improvement | |
| | | 1. The recording time limit from 8 hours changed to 12 hours. | |
| | | 2. Fixed RTMP stream key cannot use"@" issue. | |
| | | 3. Update welcome screen. | |
| 2021/04/14 | v4.8.0.14 | New Features | |
| | | 1. Added Schedule Standby and wake up function. | |

| Release Date | Version | Description | Note |
|--------------|-----------|---|------|
| | | 2. Added switch function between "simplified Chinese" and " traditional Chinese" on | |
| | | Webpage Director. | |
| | | 3. Added selections for Time Stamp (System Time Overlay): | |
| | | 3.1 hh:mm:ss. | |
| | | 3.2 hh:mm (no seconds). | |
| | | | |
| | | Improvement | |
| | | 1. CPU loading on MultiView Director change from ≥90% to ≥95%. | |
| 2021/03/12 | v4.8.0.12 | Fixed issues: Panopto information, camera login and webpage. | |
| 2021/01/08 | V4.8.0.9 | New Features | |
| | | 1. Support backup the videos to NAS (support CIFS/SMB, NFS 2 NAS protocols) | |
| | | 2. Added System Time Overlay on PGM function. | |
| | | 3. Support wireless numeric keyboard. | |
| | | | |
| | | Improvement | |
| | | 1. Fixed issue: configuration page split issue. | |
| | | 2. Fixed issue: LC-RC01 Record&Stream no light after recording stops. | |
| 2020/11/10 | v4.7.0.7 | New Features | |
| | | 1. Channel 1~4 can choose the record audio source from Audio In 1~4. | |
| | | 2. Added integration of Panopto Schedule Record and Webcast. | |
| | | 3. Support USB HID touch monitor. | |
| | | 4. The maximum number of Scenes / Overlay: from 9 to 30. | |
| | | 5. RS-232/TCP API added Backup to USB command. | |
| | | | |
| | | Improvement | |
| | | 1. Fixed issue: overlay with a solid color background will be semi-penetration on the PGM | |
| | | after v4.4.0.17. | |

| Release Date | Version | Description | Note |
|--------------|-----------|---|------|
| | | 2. Fixed issue: the configuration file of 4.4.0.X could not be imported. | |
| | | 3. Fixed issue: when using the director account to log in to the website director page, setting | |
| | | preset will pop up "Authentication denied." | |
| 2020/09/14 | v4.5.0.13 | New Features | |
| | | 1. Added Director function on the webpage. | |
| | | 2. Added the option of "IP Audio" to the source of Audio Input 1~4. | |
| | | 3. The mixing mechanism changed to Software Audio Mixer (IP Audio can be added to the | |
| | | mix) | |
| | | 4. Added CPU loading information to the Status Bar on the Director page of the GUI 5. | |
| | | RS232_RS485_TCP_protocol-LC200: Get Status command added standby status. | |
| | | | |
| | | Improvement | |
| | | 1. Fixed issue: cannot import the layout configure file produced by Layout Editor on v4.4.0.XX. | |
| 2020/07/15 | V4.4.0.19 | New Features | |
| | | 1. Added Mixer Level volume adjustment (0~125). | |
| | | 2. Added Mute/UnMute function. | |
| | | 3. All volume adjustment items added a field showing the current value. | |
| | | 4. Support exFAT formatted USB flash drives. | |
| | | 5. Added Standby and Wakeup command. | |
| | | | |
| | | Improvement | |
| | | 1. Audio Input noise. | |
| | | 2. TCP connection mechanism. | |
| 2020/06/10 | V4.4.0.17 | New Features | |
| | | 1. Compatible with Lumens' new IP Camera products: | |
| | | VC-A71P / VC-A61P / VC-BC701P / VC-BC601P / VC-BC301P | |
| | | 2. Support LC-RC01 | |

| Release Date | Version | Description | Note |
|--------------|---------|---|------|
| | | 3. Added functions on configuration page of webpage | |
| | | 3.1 Video Source Manager | |
| | | 3.2 Macro setting page (with LC-RC01) | |
| | | 4. Added function: keypad Channel 3 button can switch to Channel 4. | |
| | | 5. Added IP/RS-232 commands: | |
| | | 5.1. Set / Get Channel Source | |
| | | 5.2. Save Camera Preset | |
| | | 5.3. Set Macro command | |