

VC-TR61 Firmware Release Note

Release Date	Version	Description	Note
2025/03/17	VYW101	Bug fixes 1. Fixed the bug where, sometimes, when camera triggers the Home preset position, the location might not be accurate. 2. Fixed the bug where, sometimes, the audio on/off option was not functional after a reboot.	Note: When upgrading the firmware from VYW100 to any version, please first upgrade to the transition version MED003 , and then proceed to your desired version.
2025/02/04	VYW100	First Version	

Upgrade Guide:

(X) VYX100 -> VYW101 (Not compatible)

(O) VYX100 -> MED003 -> VYW101 or later versions (The correct upgrade path)

(O) VYX101 -> VYW102 (Direct upgrade possible)