Deployment tool 2.0 Software Release Note

| Release Date | Version | Description | Note |
|--------------|---------|---|-------------------------|
| 2025/10/31 | 1.3.11 | New Features | |
| | | 1. Added support for VC-A53 / VC-TR40N / VC-TR30 / VC-A71SN / VC-TR61 / VC-TR60A / | |
| | | VC-R31 / LC300 / LC300S / OIP-N Series / VC-B50U. | |
| | | 2. An audio warning indicator will appear in the status column for the LC300 when its | |
| | | audio status is not normal. | |
| | | Bug Fix | |
| | | 1. Fixed an issue where the Deployment tool would reset the time zone setting of the | |
| | | LC100 after restarting the tool. | |
| 2024/1/18 | 1.2.4 | New Feature | |
| | | 1. Support for VC-TR40 / VC-R30 / VC-R30,V1 / VC-A71P-HN / LC100. | |
| | | Improvements: | |
| | | 1. Improved the efficacy of the device scan function. | |
| | | 2. Improved precision in the timing of warming mail sending. | |
| | | 3. Improved overall software stability. | Added digital signature |
| | | Bug fixed | authentication. |
| | | 1. Resolved the issue where LC200 might not be discovered by Deployment Tool 2.0. | |
| | | 2. Fixed an error message bug in the group section. | |
| | | 3. Fixed the bug that prevented the search of specific IP address segments. | |
| | | 4. Addressed the issue of some computers restarting during the installation process. | |
| | | 5. Fixed the occasional failure bug during weekly or monthly scheduling. | |
| 2023/04/18 | 1.0.5 | First version. | |