

# VS-KB21\_VS-KB21N Firmware Release Note

Release Date	Version	Description	Note
2025/9/12	VYI107	<b>New Features</b> 1. The camera name can now be displayed in the KB21 search list for easier recognition. 2. The function of the Home button on the joystick can now be customized in the Shortcut Key section. 3. The maximum OIP quantity for the OIP Link function has been expanded to 24. <b>Improvement</b> 1. The camera can now be discovered over an NDI Discovery Server across different networks. <b>Bug Fix</b> 1. Fixed an issue where the VC-A71P was sometimes not displayed properly in the KB21 preview image.	
2024/02/21	VYI102	<b>New Feature</b> 1. Added OIP link function in NDI, ONVIF and VISCA over IP protocol. <b>Bug fixed</b> 1. Fixed the randomly occurring crash issue when pressing the CAM LIST or BACK button when ONVIF and RTSP's authentication are on. 2. Fixed the issue where manual focus cannot be properly tuned by the joystick button on KB21 when controlling VC-BC701P.	
2023/10/27	VYI101	First version.	

