## **OIP-N60D Firmware Release Note**

Release Date	Version	Description	Note
2025/9/12	OIB1.25	New Features	
		1. Added Voice Connect mode, which enables image switching by voice with the VC-TR60A	
		camera.	
		2. The audio source can now be chosen between Source 1 and Source 2 in the PIP/PBP layout section.	
		3. The Standby Mode button can now be enabled on the webpage.	
		4. Added a Talkback Audio function that allows selecting either USB Audio or Audio-In as the	
		source.	
		5. If either Source 1 or Source 2 loses signal while being displayed, the system switches to the	
		other source.	
		Improvements	
		1. The maximum character limit for the Path field on the Add Stream page for RTSP has been	
		increased to 127.	
2025/05/29	OIB1.19	New Features	
		1. PIP/PBP are now supported.	
		2. Talkback function is now supported.	
		3. TV Wall function is now supported.	
		4. CEC function is now supported for turning off the monitor.	
		5. Schedule reboot function is now supported.	
		6. Added the ability to filter source search results by protocol.	
		Improvements	
		1. The IP address will now remain unchanged after a firmware upgrade.	
		2. Enhanced compatibility between the OIP-N60D and the Routing switcher software.	
2025/03/06	OIB1.16	New Features	Please note that the

Release Date	Version	Description	Note
		1. Virtual USB now supports resolution changes.	N60D(OIB116) must
		2. Resolution changes are now allowed in Extender Mode.	work with the N40E
		3. Turning off UAC is now allowed in Virtual USB.	(OIA116).
		4. 802.1x is now supported.	
		5. CEC function has been added.	Cross-firmware
		6. RTSP now supports the UDP protocol.	usage should be
		Improvements	avoided.
		1. Sources can now be switched using the Menu button on the unit.	
		2. Added different authentication modes for customers who cannot use Digest authentication.	
		3. A "Full NDI not supported" message will now appear when the unsupported NDI sources are	
		detected.	
		Bug Fixes	
		1. Increased the displayed quantity limit in the search list to 256.	
		2. Fixed a bug where the IP address would sometimes change when DHCP is off.	
2024/05/15	OIB1.07	First version	