

OIP-N60D Firmware Release Note

Release Date	Version	Description	Note
2026/05/15	OIB1.36	<p>New Features</p> <ol style="list-style-type: none"> 1. Added support for Multipoint BYOM automatic signal source switching. 2. Added a new command to retrieve the current status of OIP-N devices. 3. Added a field to modify the HTTPS port directly via the web interface. 4. Added the Picture Mode feature. 5. Added Voice Connect reference audio. 6. Introduced a product key entry mechanism to unlock advanced features. <p>Improvements</p> <ol style="list-style-type: none"> 1. Establish 3 scenarios and audio calibration mechanisms into Voice Connect. <p>Bug Fixes</p> <ol style="list-style-type: none"> 1. Resolved an issue regarding device discovery via NDI. 2. Fixed an issue where enabling the Talkback feature on the Routing Switcher would cause background noise. 3. Resolved compatibility issues between the USB Extender and USB 3.0. 4. Fixed an issue where sending commands continuously over an extended period would cause the web interface to become inaccessible. <p>Resolved an issue where "No Signal" system information settings were not properly synchronized and applied to Source 2.</p>	
2025/12/5	OIB1.28	<p>New Features</p> <ol style="list-style-type: none"> 1. A custom image can be uploaded and displayed as the background when no input signal is detected. 2. Added CEC auto on/off control and a configurable device-off delay timer. <p>Improvements</p> <ol style="list-style-type: none"> 1. The product name of the OIP-N60D can be displayed properly on the AI-Box1. 	

Release Date	Version	Description	Note
		<p>2. The default HTTP Authentication has been changed to Basic.</p> <p>Bug fixes</p> <ol style="list-style-type: none"> 1. Fixed an issue where the 4K image from the VC-TR61N could not be displayed properly on the OIP-N60D. 2. Fixed an issue where the Virtual USB cannot be used when the Layout mode is enabled. 3. Fixed an issue where changing 4K source under PIP mode would cause an image issue. 4. Fixed an issue where some settings were not restored after a firmware upgrade. 5. Fixed an issue where firmware could not be updated via computer with macOS system. 	
2025/9/12	OIB1.25	<p>New Features</p> <ol style="list-style-type: none"> 1. Added Voice Connect mode, which enables image switching by voice with the VC-TR60A camera. 2. The audio source can now be chosen between Source 1 and Source 2 in the PIP/PBP layout section. 3. The Standby Mode button can now be enabled on the webpage. 4. Added a Talkback Audio function that allows selecting either USB Audio or Audio-In as the source. 5. If either Source 1 or Source 2 loses signal while being displayed, the system switches to the other source. <p>Improvements</p> <ol style="list-style-type: none"> 1. The maximum character limit for the Path field on the Add Stream page for RTSP has been increased to 127. 	
2025/05/29	OIB1.19	<p>New Features</p> <ol style="list-style-type: none"> 1. PIP/PBP are now supported. 2. Talkback function is now supported. 3. TV Wall function is now supported. 4. CEC function is now supported for turning off the monitor. 5. Schedule reboot function is now supported. 	

Release Date	Version	Description	Note
		<p>6. Added the ability to filter source search results by protocol.</p> <p>Improvements</p> <ol style="list-style-type: none"> 1. The IP address will now remain unchanged after a firmware upgrade. 2. Enhanced compatibility between the OIP-N60D and the Routing switcher software. 	
2025/03/06	OIB1.16	<p>New Features</p> <ol style="list-style-type: none"> 1. Virtual USB now supports resolution changes. 2. Resolution changes are now allowed in Extender Mode. 3. Turning off UAC is now allowed in Virtual USB. 4. 802.1x is now supported. 5. CEC function has been added. 6. RTSP now supports the UDP protocol. <p>Improvements</p> <ol style="list-style-type: none"> 1. Sources can now be switched using the Menu button on the unit. 2. Added different authentication modes for customers who cannot use Digest authentication. 3. A "Full NDI not supported" message will now appear when the unsupported NDI sources are detected. <p>Bug Fixes</p> <ol style="list-style-type: none"> 1. Increased the displayed quantity limit in the search list to 256. 2. Fixed a bug where the IP address would sometimes change when DHCP is off. 	<p>Please note that the N60D(OIB116) must work with the N40E (OIA116).</p> <p>Cross-firmware usage should be avoided.</p>
2024/05/15	OIB1.07	First version	