

Routing Switcher Release Note

Release Date	Version	Description	Note
2025/12/5	1.2.3	New Feature 1. Added PIP/PBP layouts options. Improvement 1. Improved the IP address visibility when the IP Prompt is enabled. Bug Fix 1. Fixed an issue where the OIP-N40E could not be connected in the Routing section.	
2025/03/24	1.1.11	New Features 1. Added an Audio Routing page for audio input and output functions. 2. CEC on/off option of sources can now be controlled from the Routing Switcher. 3. Display and video sources can now be added manually. 4. Added Import and Export functions for configuration. 5. The order of sources can now be rearranged by selecting a sorting option from the right-click menu. Improvements 1. Removed HLS and MPEG-TS over UDP from the stream protocol list. 2. Improved the overall user interface. Bug Fixes 1. Fixed an issue where the preview image of the source would occasionally blink. 2. Improved the overall stability of the routing switcher software.	
2024/12/03	1.0.5	First version.	

