

# Routing Switcher Release Note

Release Date	Version	Description	Note
2026/5/30	1.3.0	<p><b>New Features</b></p> <ol style="list-style-type: none"> <li>1. Added a Preset feature to save Video/Audio/USB Routing configurations.</li> <li>2. Added an Advanced feature – Virtual USB Out control switch for OIP-N40E.</li> <li>3. Added an Advanced feature – Virtual USB Out control switch for OIP-N60D.</li> <li>4. Added an Advanced feature – UAC Out Source options for OIP-N60D.</li> </ol> <p><b>Improvements</b></p> <ol style="list-style-type: none"> <li>1. Removed the option to manually add SRT streams.</li> <li>2. Added the option to modify RTSP usernames and passwords.</li> <li>3. Removed the Audio Delay option.</li> <li>4. Updated the Routing Switcher HTTP Authentication method to Basic.</li> </ol>	
2025/12/5	1.2.3	<p><b>New Feature</b></p> <ol style="list-style-type: none"> <li>1. Added PIP/PBP layouts options.</li> </ol> <p><b>Improvements</b></p> <ol style="list-style-type: none"> <li>1. Improved the IP address visibility when the IP Prompt is enabled.</li> </ol> <p><b>Bug Fix</b></p> <ol style="list-style-type: none"> <li>1. Fixed an issue where the OIP-N40E could not be connected in the Routing section.</li> </ol>	
2025/03/24	1.1.11	<p><b>New Features</b></p> <ol style="list-style-type: none"> <li>1. Added an Audio Routing page for audio input and output functions.</li> <li>2. CEC on/off option of sources can now be controlled from the Routing Switcher.</li> <li>3. Display and video sources can now be added manually.</li> <li>4. Added Import and Export functions for configuration.</li> <li>5. The order of sources can now be rearranged by selecting a sorting option from the right-click menu.</li> </ol> <p><b>Improvements</b></p> <ol style="list-style-type: none"> <li>1. Removed HLS and MPEG-TS over UDP from the stream protocol list.</li> <li>2. Improved the overall user interface.</li> </ol>	

Release Date	Version	Description	Note
		<b>Bug Fixes</b> 1. Fixed an issue where the preview image of the source would occasionally blink. 2. Improved the overall stability of the routing switcher software.	
2024/12/03	1.0.5	First version.	