

VC-TR41 Firmware Release Note

Release Date	Version	Description	Note
2025/8/29	VUF107	Bug fix 1. Adjusted the tilt control value to ensure smoother PTZ movement.	
2025/06/26	VUF105	First Version	