

# LC300\_LC300S Firmware Release Note

Release Date	Version	Description	Note
2025/07/25	LCB107	<b>New Features</b> <ul style="list-style-type: none"><li>1. Added automatic streaming option in the Stream Manager section.</li><li>2. Added commands for the Intelligent Director function.</li><li>3. Added support for the NDI Discovery Server function.</li><li>4. Added a command to switch between PVM and PGM images.</li><li>5. PVM and PGM images can now be streamed simultaneously.</li><li>6. Added PGM Audio Warning setting for low volume alerts.</li><li>7. Added option to automatically delete files after a specified period.</li></ul> <b>Improvement</b> <ul style="list-style-type: none"><li>1. SDK has been updated to v6.1.1.</li></ul> <b>Bug fix</b> <ul style="list-style-type: none"><li>1. Improved the NDI streaming stability</li></ul>	
2024/12/24	LCB103	<b>Improvements</b> <ul style="list-style-type: none"><li>1. Extended the maximum recording duration from 12 hours to 16 hours.</li></ul> <b>Fixed Bugs</b> <ul style="list-style-type: none"><li>1. Fixed the bug where the LC300 restarts and the NAS needs to be remounted.</li><li>2. Fixed the bug where setting CH1 source as 12G SDI IN results in "NO Signal" being displayed for CH1-12G SDI IN after a reboot.</li><li>3. Fixed the bug where LC300 cannot load the "Schedule" page after performing a factory reset.</li></ul>	
2024/10/18	LCB102	<b>Improvement</b> <ul style="list-style-type: none"><li>1. Changed USB description from Lumens LC300 Processor to Lumens Media Processor.</li></ul> <b>New Features</b> <ul style="list-style-type: none"><li>1. Schedule setting support iLearning Calendar.</li><li>2. Add Intelligent Director function.</li></ul>	

Release Date	Version	Description	Note
		3. Revised LC300 RTSP URL to support Lumens Virtual camera2.0. <b>Fixed Bugs</b> 1. Bug fix for potential device authentication fail. 2. Bug fix for recording cannot be started in standby mode, and the screen shows “Record Error”. 3. Bug fix for LC300 may accidentally stop recording. 4. Fixed several issue with the LC300, including stability and image problems.	
2024/05/15	LCB028	First Version.	